

TROUBLESHOOTING GUIDE INDEX FOR COMPRESSION MOLDING BMC

<u>Topic</u>	<u>Page</u>
Philosophy Of Troubleshooting Molding Problems	Compression 1
Compression Processing Problems	Compression 2
Crazing / Cracking	Compression 2
Contamination	Compression 3
Dieseling	Compression 3
Drag Marks	Compression 3
Dull Appearance	Compression 3
Flash (Excessive)	Compression 4
Flow Lines	Compression 4
Knit Lines	Compression 4
Laking	Compression 4
Nonfills Or Short Shots	Compression 5
Pin Cracking	Compression 5
Pre Cure	Compression 5
Scumming	Compression 6
Shrinkage	Compression 6
Sink Marks	Compression 6
Sticking In Mold	Compression 7
Trapped Gas (Burn Marks)	Compression 7
Warpage	Compression 7
Troubleshooting Chart and Comment Sheet	Inserts
Date Printed, Date Revised	Compression 8