

# **TROUBLESHOOTING GUIDE INDEX FOR TRANSFER MOLDING BMC**

<b><u>Topic</u></b>	<b><u>Page</u></b>
Philosophy Of Troubleshooting Molding Problems	Transfer 1
Transfer Processing Problems	Transfer 2
Crazing / Cracking	Transfer 2
Contamination	Transfer 3
Dieseling	Transfer 3
Drag Marks	Transfer 3
Dull Appearance	Transfer 4
Flash ( Excessive )	Transfer 4
Flow Lines	Transfer 4
Knit Lines	Transfer 4
Laking	Transfer 5
Nonfills Or Short Shots	Transfer 5
Pin Cracking	Transfer 5
Pre Cure	Transfer 6
Scumming	Transfer 6
Shrinkage	Transfer 6
Sink Marks	Transfer 7
Sticking In Mold	Transfer 7
Trapped Gas ( Burn Marks )	Transfer 7
Warpage	Transfer 8
Troubleshooting Chart and Comment Sheet	Inserts
Date Printed, Date Revised	Transfer 9