

# **TROUBLESHOOTING GUIDE INDEX FOR INJECTION MOLDING PHENOLIC, MELAMINE-PHENOLIC AND GRANULAR POLYESTER**

<b><u>Topic</u></b>	<b><u>Page</u></b>
Philosophy Of Troubleshooting Molding Problems	Injection 1
Injection Processing Problems	Injection 2
Ball & Socket	Injection 2
Bulge Opposite Insert	Injection 3
Cure Blister	Injection 3
Dull Appearance	Injection 3
Flash ( Excessive )	Injection 4
Flow Lines	Injection 4
Hard Spots ( Precure )	Injection 4
Injection Too Slow	Injection 5
Mold Stains	Injection 5
Mottled Surface Appearance	Injection 5
Nonfills Or Short Shots	Injection 6
Nozzle Freeze Up	Injection 6
Orange Peel	Injection 6
Rubbery Parts Or Runner	Injection 7
Screw Does Not Go "Home"	Injection 7
Screw Pickup Is Erratic	Injection 7
Screw Pickup Is Too Slow	Injection 8
Shrinkage	Injection 8
Sink Marks	Injection 9
Skin Blisters	Injection 9
Sprue Sticking	Injection 9
Sticking In Mold	Injection I0
Subgates Sticking In Mold	Injection I0
Trapped Gas ( Burn Marks )	Injection I0
Warpage	Injection I1
Wood Screwing	Injection I1
Troubleshooting Chart and Comment Sheet	Inserts
Date Printed, Date Revised	Injection 12